

Life in prison: Living conditions

Appendix A: Photographs from recent inspections

HMP Wormwood Scrubs

This servery, covered in food debris, was left uncleaned on the wing overnight.



Outside areas between the wings were strewn with litter dropped from broken windows.



HMP Erlestoke

Hole to the outside in the wall of an occupied cell.



Cell with broken furniture and a blood handprint on the wall.



Offensive graffiti in a cell.



Prisoner telephone lacking privacy in a communal kitchen area.



HMP Liverpool

Litter in an outside area.



Wall damaged by damp.



Cell covered in graffiti.



Broken window in a cell.



Shower unit with protruding electric cable.



Toilet in a cell.



Cockroach and litter on landing.



Graffiti and litter.

